


# PW series

## Portion Scale

- LCD Display
- Soft Touch Tact Switch
- lb, oz, g Convertible



ISO 9001 certified

**CAS**  
S • C • A • L • E

# PW series Portion Control Scale

## FEATURES

- Simple Weighing Scale
- Soft Touch Tact Switch
- Easy Operating
- LCD Display
- Battery Operated
- Auto Calibration
- lb, oz, g Convertible
- Function Key : On/Off, Zero, Tare, lb/oz/g


## DISPLAY & KEY BOARD



## SPECIFICATIONS

Model	PW Series
Weighing Capacity	6 × 0.005 lb / 100 × 0.1 oz / 3000g × 2 g
Display Digit	Weight(6 Digit)
Maximum Tare	Full Tare
Power Source	DC 9V(1.5V × 6 EA) / AC Adapter
Power Consumption	Approx. 0.25W
Operating Temperature	- 10°C ~ +40°C (14°F ~ 104°F)
Platter Size (inch / mm)	8.7(W) × 5.9(D) / 220(W) × 150(D)
Dimensions (inch / mm)	9.6(W) × 8.9(D) × 2.6(H) / 245(W) × 225(D) × 65(H)
Product Weight	3.3 lb / 1.5 kg

## DIMENSIONS



## CAS USA Corporation

NJ OFFICE  
99 Murray Hill Parkway  
East Rutherford, NJ 07073  
Tel: (201) 933-9002  
Fax: (201) 933-9025

<http://www.cas-usa.com>

CA OFFICE  
733 S. State College Blvd #98  
Fullerton, CA 92831  
Tel: (714) 870-1286  
Fax: (714) 870-1167



Specifications are subject to change for improvement without prior notice. 1999. 3